





MOTOR WIRING DIAGRAM

388299

4 Lead WYE Connection, Single Voltage

(3 Lead with Neutral)



To reverse rotation, interchange connections L1 and L2.

Each lead may have one or more cables comprising that lead.

In such case, each cable will be marked with the appropriate lead number.