




MOTOR WIRING DIAGRAM

414729

6 Leads Out, WYE Connection, Single Voltage

Full Winding – Across the Line Start



NOTICE

CONNECTIONS - EACH LEAD MAY CONSIST OF ONE OR MORE CABLES: L1-T1, L2-T2, L3-T3, T4, T5, T6 TOGETHER

359282

To reverse rotation, interchange leads L1 & L2.

Each lead may have one or more cables comprising that lead.

In such case, each cable will be marked with the appropriate lead number.