




108323

### Motor Wiring Diagram 6 Lead, Single Phase, Dual Voltage



Motors are connected for counter clockwise rotation.  
To reverse direction of rotation, interchange leads 2 and 4.