




MOTOR WIRING DIAGRAM

387151

Two Speed – Two Winding, Single Voltage

7 Lead (3 Lead High Speed, 4 lead Low Speed)

Constant Torque, Variable Torque, or Constant Horsepower



To reverse rotation, interchange leads 1 & 2.

Each lead may have one or more cables comprising that lead.

In such case, each cable will be marked with the appropriate lead number.