




US ELECTRICAL MOTORS

904911

Motor Wiring Diagram

3 Lead, Single Voltage, Single Phase, CW or CCW Rotation



To reverse direction of rotation, interchange leads T1 & T4.
Each lead may have one or more cables comprising that lead.
In such case, each cable will be marked with the appropriate lead number.

Connection Tag: 904911
Connection Plate: -----
Connection Decal: -----