




Accessory Connection Diagram
Surge Capacitors



SCHEMATIC

This Connection Diagram is to be used in conjunction with the main motor connection diagram supplied with the motor.

To reverse direction of rotation, interchange leads L1 & L2.

Each lead may have one or more cables comprising that lead. In such case, each cable will be marked with the appropriate lead number.