



THERMOSTATS

1. MOTOR IS EQUIPPED WITH QTY-6 (2 PER PHASE) NORMALLY CLOSED THERMOSTATS IN THE MOTOR WINDING. THERMOSTATS ARE SET TO OPEN AT HIGH TEMPERATURE.
2. THERMOSTATS MUST NOT BE USED TO SWITCH ABOVE 18 AMPS AT 24 VDC OR 12 AMPS AT 230 VAC.



| |
|---------------------------------------|
| ACCESSORY LISTING |
| QTY-6 N.C. THERMOSTATS (MAIN & SPARE) |

| | | | | | | | |
|--------------------------------|---|----------|------------------------------------|---------------------|--------------------------------|---------------------|------------|
| REVISION DESCRIPTION FOR: MISC | SCALE NONE | UNITS IN | DRAWING, CONNECTION DIAGRAM | | NIDEC MOTOR CORPORATION | | |
| STL0211 - UPDATED FORMAT. | TOLERANCES ON DIMENSIONS (UNLESS OTHERWISE SPECIFIED) | | | | | | |
| MATERIAL: | INCHES | mm | ISSUED BY R. KING | APPROVED BY C. CADE | REVISION DATE 23-FEB-11 | | |
| --- | ANGLES X°= ±1° | | CODE | DWG NO. 0853506 | REV E | SHEET NUMBER 1 OF 1 | DWG SIZE A |