



THERMOSTATS

1. MOTOR IS EQUIPPED WITH QTY-6 (2 PER PHASE) NORMALLY CLOSED THERMOSTATS IN THE MOTOR WINDING. THERMOSTATS ARE SET TO OPEN AT HIGH TEMPERATURE.
2. THERMOSTATS MUST NOT BE USED TO SWITCH ABOVE 18 AMPS AT 24 VDC OR 12 AMPS AT 230 VAC.



ACCESSORY LISTING
QTY-6 N.C. THERMOSTATS (MAIN & SPARE)

REVISION DESCRIPTION FOR: MISC	SCALE NONE	UNITS IN	DRAWING, CONNECTION DIAGRAM		NIDEC MOTOR CORPORATION		
STL0211 - UPDATED FORMAT.	TOLERANCES ON DIMENSIONS (UNLESS OTHERWISE SPECIFIED)						
MATERIAL:	INCHES	mm	ISSUED BY R. KING	APPROVED BY C. CADE	REVISION DATE 23-FEB-11		
---	ANGLES X°= ±1°		CODE	DWG NO. 0853506	REV E	SHEET NUMBER 1 OF 1	DWG SIZE A