





Motor Wiring Diagram
IEC Motors
9 Lead, Dual Voltage (WYE Conn.)



To reverse direction of rotation, interchange leads L1 & L2.

Each lead may have one or more cables comprising that lead.
In such case, cable will be marked with the appropriate lead number.