




MOTOR WIRING DIAGRAM

466703

12 Lead, Single Voltage, Wye Start – Delta Run or Part Winding Start



Revised: 1/8/2014