





906066

Motor Wiring Diagram 12 Lead, Dual Voltage, WYE Connection, with Thermal Protector

(9 Motor Lead & 3 Protector Leads)



To reverse direction of rotation interchange connections L1 and L2.

Each lead may have one or more cables comprising that lead.
In such case each cable will be marked with the appropriate lead number.