




897847

Motor Wiring Diagram Powerblock Connection 12 Lead



2 Delta	1 Delta	1 Delta-WYE
60 Hz 200V	60 Hz 400V	60 Hz 575V
60 Hz 230V	60 Hz 460V	60 Hz 600V
50 Hz 190V	50 Hz 380V	
L1 L2 L3	L1 L2 L3	L1 L2 L3

To reverse direction of rotation interchange connections L1 and L2.

Each lead may have one or more cables comprising that lead.
In such case each cable will be marked with the appropriate lead number.